

FIG. 1

FIG. 1 is a perspective view of a mechanical assembly. A large cylindrical component 1 is connected via a shaft 20 to a rectangular block 3. Block 3 has two circular features 23. A bracket 24 is attached to block 3. A cylindrical component 4 is positioned below block 3. A curved component 50 is at the bottom right, with a small rectangular feature 99. Various other components are labeled with numbers 1, 2, 3, 4, 5, 6, 7, 8, 20, 23, 24, 25, 50, 51, 52, and 99. Arrows II and III indicate directions of movement or force.

A schematic diagram of a printing system. A horizontal line represents a substrate (1). On the left is a large circular component (2). Above the substrate, from left to right, are a processing unit (20) with sub-components 21, 23, and 24, and a unit (7) containing a wavy line and four downward arrows. Below the substrate, a series of four oval shapes (6) are shown with downward arrows pointing to them. To the right of these are three circular components (3, 4, 5) and a curved member (8) with a double line (12) on its inner surface.

FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9





FIG. 10






FIG. 12




FIG. 13




FIG. 14

FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20

